

WARNING

The original equipment manufacturer has issued a technical service bulletin (TSB) which may address the cause of your original turbocharger failure.


Damage to your turbo from not following this TSB is NOT covered by warranty.

The following components must be verified for proper function:

1. **Wastegate Solenoid**
2. **Plastic/Rubber air supply lines must have NO restrictions or leaks.**

The technical service bulletin has procedures and details which should be followed in entirety.

SERVICE BULLETIN INFORMATION



Use camera to
scan for more info



OR VISIT

Detroit Service Information Bulletin:

<https://static.nhtsa.gov/odi/tsbs/2017/MC-10142099-9999.pdf>