


TECHNICAL SERVICE BULLETIN


Oil Filter Bypass Valve Must be Updated

NEEDS UPDATE PERFORMED



NO PAINT:
needs update performed.

UPDATED



PAINT:
revised bypass has been installed.

APPLICATION INFORMATION: ALL ISM, QSM, ISX, QSX ENGINES

Failure to update the bypass will allow unfiltered oil into the turbocharger bearings and cause it to fail, voiding the warranty.


TSB160017 New Oil Bypass Valve
4908439 Installation Instructions



TECH SERVICE HOT LINE

Call (844) 476-8500

8:00 AM – 6:00 PM EST



Use camera to
scan for more info